


Pipe Segment 2B-23 to 2B-22 – 2/19/2010

- Reduced capacity due to grease and tuberculation
- Dewatering required to perform television inspection
- Pipe fully surcharges when Cherry Street Pump Station is running



Pipe Segment 2B-23 to 2B-22 – 9/11/2014

- Reduced capacity due to grease and tuberculation
- Dewatering required to perform television inspection



Approximate flow Level when Cherry Street Pump Station is running


Pipe Segment 2B-12A to 2B-12 – 3/21/2013

- Water level increases throughout pipe during inspection from March 2013.
- Camera under water at STA 2+05.



Manhole 2B-23

3/18/2013



Surcharge Level
When Cherry Street
Pump Station is Pumping

Manhole 2B-17

3/18/2013



Manhole 2B-16

3/18/2013



Manhole 2B-15

3/18/2013



Manhole 2B-14

3/18/2013



Manhole 2B-13

3/18/2013



Manhole 2B-8

3/13/2013



Manhole 2B-7B

3/13/2013



Manhole 2B-6

3/13/2013



Manhole 2B-5

3/13/2013



Manhole 2B-2

3/13/2013

